

**Crow Lane Landfill  
Complaint Response Report**

ver. 08/09

Date: <u>10/13/09</u>		Time of Complaint: <u>3:59 pm</u>	
Complainant		Response	
Name: <u>Michael Frey</u>		Time: <u>4:37 pm</u>	
Address: <u>Swilson way Newburyport</u>		By Name: <u>Peter C. Laro</u>	
Odor	YES <input type="radio"/> <b>NO</b> <input checked="" type="radio"/> (circle one)		
Other: _____	Initial: <u>PP</u>		

Were odors detected during the response? No

Odor Intensity (1-5 scale) NA Odor Duration: \_\_\_\_\_

Odor Description/Type: NA

Location	H2S Readings During Response				Comments
Driveway of house	0.001	0.001	0.001	0.000	<del>None</del> Sweet odor detected

Weather Conditions at time of response: 53°F

Wind: \_\_\_\_\_ Direction (From) N Speed: 5-7 mph

Was Perimeter Landfill Survey Performed following the complaint? YES ☐ **NO** ☒  
(circle one)

**Crow Lane Landfill  
Complaint Response Report**

ver. 08/09

Date: <u>10/13/09</u>		Time of Complaint: <u>3:29 pm</u>	
Complainant		Response	
Name: <u>Bill Woodbury</u>		Time: <u>4:27 pm</u>	
Address: <u>3 charnanski</u>		By Name: <u>Peter Lintner</u>	
Odor	YES <input type="radio"/> NO <input checked="" type="radio"/> (circle one)		
Other: _____	Initial: <u>PL</u>		

Were odors detected during the response? No

Odor Intensity (1-5 scale) NA Odor Duration: \_\_\_\_\_

Odor Description/Type: NA

Location	H2S Readings During Response				Comments
W. Side of house	0.003	0.002	0.000	0.002	No odor detected

Weather Conditions at time of response: 54°F, cloudy

Wind: Direction (From) ~~NE~~ NW Speed: 0-3 mph

Was Perimeter Landfill Survey Performed following the complaint?

YES ☐ NO ☒  
(circle one)

**Crow Lane Landfill  
Complaint Response Report**

ver. 08/09

Date: <u>10/13/09</u>		Time of Complaint: <u>10:30 AM</u>	
Complainant		Response	
Name: <u>Nancy Kladonski</u>		Time: <u>12:00 PM</u>	
Address: <u>18 Wildwood Dr Newbury Port</u>		By Name: <u>Peter Lubinski</u>	
Odor	YES <input type="radio"/> NO <input checked="" type="radio"/> (circle one)		
Other: _____	Initial: <u>PL</u>		

Were odors detected during the response? No

Odor Intensity (1-5 scale) NA Odor Duration: NA

Odor Description/Type: NA

Location	H2S Readings During Response				Comments
<u>Front of house</u>	<u>0.002</u>	<u>0.002</u>	<u>0.002</u>	<u>0.002</u>	<u>No odor detected</u>

Weather Conditions at time of response: lt rain

Wind: Direction (From) NA Speed: NA

Was Perimeter Landfill Survey Performed following the complaint?

YES ☐ NO ☒  
(circle one)

**Crow Lane Landfill  
Complaint Response Report**

ver: 08/09

Date: <u>10/13/09</u>		Time of Complaint: <u>8:46 AM</u>	
Complainant		Response	
Name: <u>Patricia Corson</u>		Time: _____	
Address <u>29 Wildwood Dr.</u> <u>Hambury part</u>		By Name: <u>Peter Lukanis</u>	
Odor	YES <input type="radio"/> NO <input checked="" type="radio"/> (circle one)		
Other: _____	Initial: <u>PL</u>		

Were odors detected during the response? No

Odor Intensity (1-5 scale) NA Odor Duration: NA

Odor Description/Type: NA

Location	H2S Readings During Response				Comments
End of driveway	0.002	0.002			No odors noted.
Front of house	0.002	0.002	0.002	0.002	

Weather Conditions at time of response: 42°F, raining

Wind: Direction (From) NA Speed: NA

Was Perimeter Landfill Survey Performed following the complaint? YES NO  
(circle one)

Crow Lane Landfill  
Complaint Response Report

Date: <u>10/31/09</u>	Time of Complaint: <u>7:46 AM</u>
Complainant Name: <u>Nancy Kłodenski</u>	Response Time: <u>8:06 AM</u>
Address: <u>18 Wildwood Dr.</u>	By Name: <u>Peter Velazquez</u>
Odor: YES <input type="radio"/> NO <input checked="" type="radio"/> (circle one)	Initial: <u>PP</u>
Other: _____	

Were odors detected during the response? No

Odor Intensity (1-5 scale) NA Odor Duration: NA

Odor Description/Type: NA

Location	H2S Readings During Response				Comments
Front of house	0.002	0.002	0.002	0.002	No odors detected

Weather Conditions at time of response: 49°F

Wind: Direction (From) NA Speed: NA

Was Perimeter Landfill Survey Performed following the complaint? YES ☒ NO ☐ (circle one) 7:30 AM

Crow Lane Landfill  
Complaint Response Report

ver. 08/09

Date: <u>10/13/09</u>	Time of Complaint: <u>5:52 am</u>
Complainant	Response
Name: <u>Brenda Reffett</u>	Time: <u>6:17 AM</u>
Address: <u>Shaws Supermarket</u>	By Name: <u>Peter Wauis</u>
Odor <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO (circle one)	Initial: <u>PP</u>
Other: _____	

Were odors detected during the response? No

Odor Intensity (1-5 scale) NA Odor Duration: NA

Odor Description/Type: NA

Location	H2S Readings During Response				Comments
Front of Shaws Supermarket	0.002	0.002	0.002	0.002	No odor noted.

Weather Conditions at time of response: Raining

Wind: Direction (From) NA Speed: NA

Was Perimeter Landfill Survey Performed following the complaint? ☒ YES ☐ NO  
(circle one)

## ver. 08/09

Were odors detected during the response? Yes

Odor Intensity (1-5 scale) 1-2 Odor Duration: \_\_\_\_\_

Odor Description/Type: H<sub>2</sub>S odor

Weather Conditions at time of response: \_\_\_\_\_

Was Perimeter Landfill Survey Performed following the complaint? YES NO  
(circle one)

**Crow Lane Landfill  
Complaint Response Report**

ver. 08/09

Date: <u>10/14/09</u>		Time of Complaint: <u>12:44 pm</u>	
Complainant		Response	
Name: <u>Nancy Klodenski</u>		Time: <u>1:24 pm</u>	
Address: <u>18 wild wood dr Newberry port</u>		By Name: <u>Peter L. Jones</u>	
Odor	YES <input type="radio"/> <b>NO</b> <input checked="" type="radio"/> (circle one)		
Other: _____	Initial: <u>PP</u>		

Were odors detected during the response? No

Odor Intensity (1-5 scale) NA Odor Duration: \_\_\_\_\_

Odor Description/Type: NA

Location	H2S Readings During Response				Comments
Front of house	0.004	0.002	0.002	0.002	No odor noted

Weather Conditions at time of response: Sunny, lt. wind

Wind: Direction (From) NW Speed: 3-6 mph

Was Perimeter Landfill Survey Performed following the complaint? YES ☐ **NO** ☒  
(circle one)



**Crow Lane Landfill  
Complaint Response Report**

ver. 08/09

Date: <u>10/19/09</u>		Time of Complaint: <u>12:35 pm</u>	
Complainant		Response	
Name: <u>Nancy Klodenski</u>		Time: <u>1:27 pm</u>	
Address <u>18 Wildwood Dr.</u> <u>Hamburgport</u>		By Name: <u>Peter Velazquez</u>	
Odor	YES <input type="radio"/> <b>NO</b> <input checked="" type="radio"/> (circle one)		
Other: _____	Initial: <u>VP</u>		

Were odors detected during the response? NO

Odor Intensity (1-5 scale) NA Odor Duration: \_\_\_\_\_

Odor Description/Type: NA

Location	H2S Readings During Response				Comments
Floral house	0.002	0.001	0.001	0.001	No odor noticed upon arrival

Weather Conditions at time of response: \_\_\_\_\_

Wind: Direction (From) \_\_\_\_\_ Speed: \_\_\_\_\_

Was Perimeter Landfill Survey Performed following the complaint? **YES** **NO**  
(circle one)

Crow Lane Landfill  
Complaint Response Report

ver: 08/09

Date: <u>10/19/09</u>	Time of Complaint: <u>7:22 Am</u>
Complainant Name: <u>Bill woodbury</u>	Response Time: <u>7:40 Am</u>
Address <u>3 charnawsky Dr.</u> <u>Norburyport.</u>	By Name: <u>Peter L. Laisis</u>
Odor <b>YES</b> <b>NO</b> (circle one)	
Other: _____	Initial: _____

Were odors detected during the response? No

Odor Intensity (1-5 scale) NA Odor Duration: NA

Odor Description/Type: NA

Location	H2S Readings During Response				Comments
Front of house	0.005	0.004	0.005	0.004	No odor noted upon arrival

Weather Conditions at time of response: 41°F, No wind

Wind: Direction (From) NA Speed: NA

Was Perimeter Landfill Survey Performed following the complaint? **YES** **NO**  
(circle one)